

Low Voltage Easy-Touch Pro

Performance Verification Manual

Version 2025.3.0

CIRRIIS[®]

A KOMAX COMPANY

Low Voltage Easy-Touch Pro

Performance Verification Manual

Version 2025.3.0

Copyright 2025 by Cirris, Inc.

All Rights Reserved

Cirris, Inc.
401 North 5600 West
Salt Lake City, UT 84116
USA

Table of Contents

<i>Introduction</i>	1
Low Voltage Easy-Touch Pro ONLY.....	1
Performance Check Kit	2
Verification Interval	2
Quality System.....	2
<i>Setting Up</i>	3
Performance Verification Certificate and Data Sheet.....	3
Install Add-On Scanners.....	3
Plug in the Tester	3
Parts List.....	3
<i>Creating a Category</i>	4
<i>Importing the Test Files</i>	6
<i>Signal Routing System Test</i>	9
<i>Resistance Measurement System Test</i>	14
<i>Resistance Threshold System Test</i>	17
500k Ω	17
1M Ω	19
5M Ω	20
<i>Capacitance Measurement System Test</i>	21
<i>4-Wire Measurement System Test</i>	22
<i>Appendix</i>	23


Introduction



Low Voltage Easy-Touch Pro ONLY

Important! This manual is for use in the performance verification of Easy-Touch Pro **Low Voltage** testers only. Users of Easy-Touch Pro High Voltage testers, those capable of performing Hipot at up to 1500 volts DC or 2000 volts DC, should use the standard *Easy-Touch Pro Performance Verification Manual*.

Easy-Touch Pro testers are clearly labeled on the front panel as either **High Voltage** or **Low Voltage** units.



Performance Check Kit

The Easy-Touch Pro Performance Verification (Check) Kit allows you to verify the calibration and proper operation of the Low Voltage Easy-Touch Pro tester. Each performance verification kit has a life cycle of two years from the time of purchase. At the end of two years, you can recalibrate or replace the kit. The components for this performance verification kit are tested with instruments traceable to the National Institute of Standards and Technology (NIST).

Verification Interval

Performance Verification of the Low Voltage Easy-Touch Pro should be done annually at a minimum and any time the tester is not operating properly. If a step in the performance verification procedure fails, send the tester back to Cirris for repair. No external adjustments can be made to fix the tester.

Quality System

For information on setting up a quality system see the appendix in this manual.

Setting Up

Performance Verification Certificate and Data Sheet

You will find the Low Voltage Easy-Touch Pro Performance Verification Certificate and Verification Data Sheet at the end of this manual. You can record verification data on these documents for your records. If you use these documents, make photocopies to maintain master copies for future use.

Install Add-On Scanners

The examples in this manual use an Easy-Touch Pro with no expansion boxes.

Install add-on scanners if you have any. For instructions, see your Easy-Touch Pro User Manual.



Note: Before performing any of the tests in this manual, remove all adapters from the tester (including from the add-on boxes) except for the adapters needed for verification. Failing to remove unnecessary adapters could result in the wrong signature and cause a failure even when the tester is functioning correctly.

Plug in the Tester

Plug one end of the power cord into the tester. Plug the other end into a grounded outlet.



Parts List

Make sure you received the following parts:

- Zero Ohm Adapter



- Capacitance/Fourwire Adapter



- Resistor Leak Adapter




Creating a Category

In the Easy-Wire® software, you can organize test programs into groups by assigning them to different categories. You can also create custom test program categories. The steps below illustrate how to create a category for your verification test files.


1. On the back of your Easy-Touch Pro tester, push in the power button for a few seconds to power on the tester.




2. When the “User Login” window opens, log in to Easy-Wire.



3. In the Easy-Wire main menu, press ‘Utilities’.




4. Press **'Category Maintenance'**.




5. In the "Categories" window, do the following:

- a. Select <New Category> in the first text box.
- b. Enter a name, such as Verification, for the category in the second text box.
- c. Check the "Test Program" box.
- d. Press **'Add'**.
- e. Press **'Done'**.



6. Press **'Done'** to return to the main menu.




Importing the Test Files


1. In the Easy-Wire main menu, select the category you created in the previous section and press **'Utilities'**.



2. Press **'Import'**.




3. Press 'Import .WIR File'.



4. Navigate to the file path below:


```
C:\Users\Public\  
Public Documents\  
Cirris\easywire  
\CalFiles\EasyTouch
```



5. Select the files needed for verification of a low voltage tester:

- 1M Threshold.WIR
- 4-Wire Measurement.WIR
- 5M Threshold.WIR
- 500k Threshold.WIR
- Cap Measurement.WIR


Press 'Open'.




6. In version 2019.1.0 and later, multiple selected files are imported as a group and it won't be possible to select a destination category (one can be assigned later by right-clicking a program name in the Main Menu).

In earlier versions, or when files are imported individually, the test will be displayed. Do the following:


- a. From the drop down menu, select the verification file category you created.
- b. Press 'Import'.



7. Press 'Done'.



8. Press 'Done' to return to the main menu.




Note: To ensure that you always have the correct test files, re-import the files any time you update Easy-Wire or if you have not run the test in a while. Re-importing test files guarantees version control.

Signal Routing System Test


1. Install the Zero Ohm Adapter in the J1-J2 position as shown.



2. In the Easy-Wire main menu, press **'Create Test'**.




3. Press **'Learn Signature Test Program'**.




4. In the “Learn Attached Device” window, do the following:

- Set the “Connection Resistance” to **0.1 Ohm**.
- Set the “LV Insulation Resistance” to **5.00 MOhm**.
- Clear** all component boxes.
- If your software contains the “**Use Defaults For Adapters With Shared Signatures**” box, make sure it is NOT checked.
- Click ‘**Learn Attached Device**’.




5. In the window that opens, select **AHED-64** as the adapter type and click **OK**.



6. In order to view the signature of the adapter, you must be in a Signature Mode test.


Go to Tab 2 Set Test Defaults to verify that the Test Method is set to **Signature Single Test** or **Signature Continuous Test**.

If you are not in a Signature Test method, click on the drop-down box next to Test Method




7. A separate window will open and display multiple test options. In the “Select Test Method” column, select a Signature test.


- **Continuous Test:** Similar to a Single Test but continues repeating until all errors are solved. A Continuous Test allows the operator to move the cable around in an effort to catch intermittent failures such as loose connections. Test will continue to run until the Stop button is pressed.
- **Signature Single Test:** The tester will perform the specified low voltage tests once. This method is fastest.



8. To view the signature, press ‘**Save As**’, but do not save the test!




9. If the displayed signature matches the correct signature on the verification data sheet under “Signal Routing System Test”, check **Pass**; otherwise, check **Fail**.




Note: If you do not see the signature displayed and the box reads “untitled”, change the test method to Signature Single Test by canceling, selecting Tab 2, and changing the test method to Signature Single Test. Click Save again to see the signature appear in the box.

10. When you are finished viewing the signature, press **Cancel**.

11. In the Test Program Editor, press **Done**.



12. Select “Abandon changes and return to the main menu” and press **OK**.



13. Install the Zero Ohm Adapter in the J3-J4 position, and repeat steps 2-12. In step 9, you can compare the signature with correct signature in Table 1 below.



14. If you installed add-on scanners, move the Zero Ohm Adapter to each subsequent "J" position and repeat steps 2-12 for each test.

Table 1 lists the correct signatures for the adapter "J" positions.

Zero Ohm "J" Position Signatures			
"J" Position	Correct Signature	"J" Position	Correct Signature
J1-J2	7F5527-6M020	J17-J18	8CE799-6M020
J3-J4	94C424-6M020	J19-J20	18483C-6M020
J5-J6	5CC1A1-6M020	J21-J22	3476BF-6M020
J7-J8	D3A34A-6M020	J23-J24	B5D5D5-6M020
J9-J10	51A15E-6M020	J25-J26	1E83A5-6M020
J11-J12	C50EFB-6M020	J27-J28	8A2C00-6M020
J13-J14	E93078-6M020	J29-J30	A61283-6M020
J15-J16	719A99-6M020	J31-J32	3BA461-6M020

Table 1

15. Remove the Zero Ohm Adapter.




Resistance Measurement System Test


1. Install the Resistor Leak Adapter in the J1-J2 position as shown.




2. In the Easy-Wire main menu, press **'Create Test'**.




3. Press **'Learn Signature Test Program'**.



4. In the “Learn Attached Device” window, do the following:
 - a. Set the “Connection Resistance” to **0.1 Ohm**.
 - b. Set the “LV Insulation Resistance” to **5.00 MOhm**.
 - c. **Clear** all component boxes.
 - d. If your software contains the “**Use Defaults For Adapters With Shared Signatures**” box, make sure it is **NOT** checked.
 - e. Click ‘**Learn Attached Device**’.




5. Record each Measured value in the “Hardware Status Update” window on the verification data sheet under “Resistance Measurement System Test”. If the value is between the minimum and maximum limits shown in Table 2 below, check **Pass**; otherwise, check **Fail**.




Resistance Measurement			
Resistor Positions	Correct Resistance	Minimum Limit	Maximum Limit
J1B002-J1B004	10.00 Ω	9.80 Ω	10.20 Ω
J1B003-J1B005	100.0 Ω	98.9 Ω	101.1 Ω
J1B006-J1B008	1,000 Ω	989.9 Ω	1,010.1 Ω
J1B007-J1B010	9,090 Ω	8,999 Ω	9,181 Ω
J1B013-J1B015	85.00K Ω	84.15K Ω	85.85K Ω
J1B016-J1A016	404.1K Ω	363.69K Ω	444.51K Ω
J1A020-J1A021	3.806M Ω	3.4254M Ω	4.1866M Ω
J1A022-J1A023	592.0K Ω	532.8K Ω	651.2K Ω

Table 2

6. When you are done recording the measured values, press **'OK'**.



7. Press **'Cancel'** to return to the main menu.



Resistance Threshold System Test


500k Ω

1. Ensure that the Resistor Leak Adapter is in the J1-J2 position as shown.




2. In the Easy-Wire main menu, select "500k Threshold" from the list, and press 'Test'.


Note: The proper category must be selected to view the verification files as a group.



3. When the information bar at the top displays "Ready to Test", press 'Start'.




4. The test window should display “HIGH RESISTANCE ERROR”. If the failed points are from J1B016 to J1A016, check **Pass** on the verification sheet under “Resistance Threshold System Test, 500k Ω ”; otherwise check **Fail**.



Note: The actual measured value for this part of the test is irrelevant and does not need to be recorded.

5. Press ‘Done’ to return to the main menu.



1M Ω


1. Ensure that the Resistor Leak Adapter is in the J1-J2 position as shown.



2. In the Easy-Wire main menu, select “1M Threshold” and press ‘**Test**’.

3. When the information bar at the top displays “Ready to Test”, press ‘**Start**’.

4. The test window should display “HIGH RESISTANCE ERROR”. If the failed points are from J1A022 to J1A023, check **Pass** on the verification sheet under “Resistance Threshold System Test, 1M Ω ”; otherwise check **Fail**.



Note: The actual measured value for this part of the test is irrelevant and does not need to be recorded.

5. In the test window, press ‘**Done**’ to return to the main menu.
-


5M Ω

1. Ensure that the Resistor Leak Adapter is in the J1-J2 position as shown.



-
2. In the Easy-Wire main menu, select “5M Threshold” and press ‘Test’.
-
3. When the information bar at the top reads “Ready to Test”, press ‘Start’.
-

4. The test window should display “HIGH RESISTANCE ERROR”. If the failed points are from J1A020 to J1A021, check **Pass** on the verification sheet under “Resistance Threshold System Test, 5M Ω ”; otherwise check **Fail**.



Note: The actual measured value for this part of the test is irrelevant and does not need to be recorded.

5. In the test window, press ‘Done’ to return to the main menu.
-

Capacitance Measurement System Test


1. Install the Capacitance/4-Wire Adapter in the J1-J2 position as shown.



2. In the Easy-Wire main menu, select “Cap Measurement” and press ‘Test’.
3. When the information bar displays “Ready to Test”, press ‘Start’.

4. The information bar will display “Bad.” Record the Measured Value on the verification data sheet under “Capacitance Measurement System.”

Check **Pass** if the measured value is between the minimum and maximum limits shown in Table 8. Otherwise check **Fail**.



Capacitance Measurement		
Correct Capacitance	Minimum Capacitance	Maximum Capacitance
1.41 μ F	1.27 μ F	1.55 μ F

Table 8

5. In the test window, press ‘Done’ to return to the main menu.

4-Wire Measurement System Test

1. Ensure that the Capacitance/4-Wire Adapter is in the J1-J2 position as shown.



2. In the Easy-Wire main menu, select "4-Wire Measurement", and press **'Test'**.


3. When the information bar reads "Ready to Test", press **'Start'**.

4. The information bar will read "Bad".

5. Verify that the "Bad 4W Resistor" reads J1A001 and J1A003.

6. On the verification data sheet under "4-Wire Measurement System", check **Pass** if the measured value is between 195 and 205 mOhm. Otherwise check **Fail**.

7. Press **'Done'**.



8. Remove the Capacitance/4-Wire Adapter from the tester.



Appendix

The following references and suggestions may be useful to those new to formal calibration and quality practices.

Standards

The ANSI/NCSL Z540.3 and ISO 17025 standards document requirements for the calibration of measuring and test equipment. The Z540.3 standard can be acquired from the National Conference of Standards Laboratories International (NCSL) at www.ncsli.org. The ISO standard can be acquired from the International Standards Organization (ISO) on their web site www.iso.net. Both standards provide valuable insight into calibration best practices.

Foundational Calibration Principles

Recall System

Use a tickler card file or computerized database recall system to ensure that measurement equipment is calibrated on schedule. This system should include calibration dates, due dates, calibration sources, and any other pertinent information.

Verification Labels

After calibration / verification, the quality standards require that a label indicating the calibration status be affixed to the instrument. This ensures that users will have ready access to the calibration status and helps avoid the inadvertent use of uncalibrated, or out-of-calibration, measurement equipment. The labels should include the instrument serial number, the calibration date, the calibration due date, and the name of the individual that performed the calibration. A good source of inexpensive labels is United Ad Label (www.unitedadlabel.com).

Measurement Uncertainty

Older standards referenced TUR (test uncertainty ratio) or TAR (test accuracy ratio) and suggested a 4:1 ratio between the accuracy of the measurement instrument and the accuracy of the instrument being calibrated. However, current standards emphasize the calculated measurement uncertainty. Many excellent resources that address the subject are available on the Internet.

Performance Verification Certificate

The Performance Verification Certificate is a record of who, when, and with what equipment the instrument was calibrated / verified. A suggested Performance Verification Certificate is provided later in this appendix.

Calibration Data

Supporting verification measurement data can be recorded as described in this manual.

Traceability

Traceability refers to each unbroken link of valid verifications going back to national standards such as those maintained by the NIST in the United States. To maintain traceability, qualified personnel must perform the performance verification under controlled conditions, using correctly calibrated instruments with acceptable accuracy.

Name and Address of Organization:			
Certificate Number:		Performed by:	
Date:		Due Date:	
Applicable Quality Standard(s):		Procedure: Easy-Touch Pro LV Performance Verification-Version _____	
Temperature:		Relative Humidity:	
Tester Serial Number:			
Instruments used:	Serial Number	Cal. Date	Due Date
Zero Ohm Adapter			
Resistor Leak Adapter			
Capacitance/Fourwire Adapter			
Statement of Traceability:			
Certified by:			

Low Voltage Easy-Touch Pro Verification Data Sheet

Date: _____

Tester Serial Number: _____

Tests Performed By: _____

Signal Routing System

J Position for Adapter	Correct Signature	Displayed Signature	Pass	Fail
J1-J2	7F5527-6N020			
J3-J4	94C424-6N020			
J5-J6	5CC1A1-6N020			
J7-J8	D3A34A-6N020			
J9-J10	51A15E-6N020			
J11-J12	C50EFB-6N020			
J13-J14	E93078-6N020			
J15-J16	719A99-6N020			
J17-J18	8CE799-6N020			
J19-J20	18483C-6N020			
J21-J22	3476BF-6N020			
J23-J24	B5D5D5-6N020			
J25-J26	1E83A5-6N020			
J27-J28	8A2C00-6N020			
J29-J30	A61283-6N020			
J31-J32	3BA461-6N020			

Resistance Measurement System

Resistor Positions	Correct Resistance	Minimum Limit	Maximum Limit	Displayed Value	Pass	Fail
J1B002-J1B004	10.00 Ω	9.80 Ω	10.20 Ω			
J1B003-J1B005	100.0 Ω	98.9 Ω	101.1 Ω			
J1B006-J1B008	1,000 Ω	989.9 Ω	1,010.1 Ω			
J1B007-J1B010	9,090 Ω	8,999 Ω	9,181 Ω			
J1B013-J1B015	85.00K Ω	84.15K Ω	85.85K Ω			
J1B016-J1A016	404.1K Ω	363.69K Ω	444.51K Ω			
J1A020-J1A021	3.806M Ω	3.4254M Ω	4.1866M Ω			
J1A022-J1A023	592.0K Ω	532.8K Ω	651.2K Ω			

Resistance Threshold System

- 500 k Ω Test

High Resistance Error between:	Pass	Fail
J1B016 and J1A016		

- 1 M Ω Test

High Resistance Error between:	Pass	Fail
J1A022 and J1A023		

- 5 M Ω Test

High Resistance Error between:	Pass	Fail
J1A020 and J1A021		

Capacitance Measurement System

Correct Capacitance	Minimum Capacitance	Maximum Capacitance	Displayed Measured Value	Pass	Fail
1.41 μ F	1.27 μ F	1.55 μ F			

4-Wire Measurement System

Bad 4W Resistor Error between J1A001 and J1A003	Minimum Value	Maximum Value	Pass	Fail
$0.2 \Omega \pm 2\% \pm 0.001 \Omega$	0.195 Ω	0.205 Ω		